
INSTALLATION INSTRUCTIONS

PLASMA DISPLAY STATIC MOUNT OS-PST-0705




Figure 1

- (1) Plasma Static Mount
- (1) Latching Flag (attached)
- (1) 10-24 Nylock Nut (attached)

- (1) 10-24 x .5 Undercut FH Screw (attached)
- (1) PSB Package for the Specific Plasma
- (1) Nylon Washer
.500" OD x .312" ID x .0312" (attached)

BEFORE PROCEEDING: Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

WARNING! ALL COMPONENTS MUST BE SECURELY FASTENED TO A STRUCTURAL MEMBER CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF ALL COMPONENTS PLUS THE EQUIPMENT BEING MOUNTED. IF IT CANNOT SUPPORT THIS WEIGHT, THE STRUCTURE MUST BE REINFORCED. THE MAXIMUM WEIGHT TO BE INSTALLED ON THE COLUMN IS 175 POUNDS (79.38 KG).

1. Anchor the mount to wall studs or supporting framework securely (see WARNING).
2. Attach included PSB brackets to display using the instructions included with the PSB package.
3. Make sure the flag is lowered to the side before attempting to place the display on the mount.
4. With the aid of another person, lift the display up to the mount, align the mounting buttons with the teardrop slots in the mount, and set the display into place (see Figure 2).
5. Position (raise) the flag to secure the display (see Figure 2).




Figure 2