INSTALLATION INSTRUCTIONS

BRACKET
SSC-4

The SSC bracket is designed for adding additional security to installations. By installing the SSC, a locking device can be placed to obscure access to fastening hardware.

Unpack and check contents (see Figure 1):

Figure 1.

(2) SSC-3 (5/16" clearance hole)	(1) M4 Flat Washer
(3) SSC-1 (#10 clearance hole)	(1) M5 Flat Washer
(1) 10-24 x .25" Phillips Head Cap Screw	(1) M6 Flat Washer
(1) 5/16-18 x .625" Button Head Cap Screw	(1) 3/16" Hex Key

1. Remove one of the 10-24 screws from the projector's SLB interface bracket (see Figure 2).


Figure 2.

2. Replace the 5/16" set screw of the RPA projector mount with the supplied 5/16" Button Head Cap Screw and an SSC-3 (see Figure 3).


Figure 3.

3. Install an SSC-1 bracket in one pitch and one roll adjustment screw on the RPA projector mount (see Figure 4 & Figure 5).

Figure 4.

Figure 5.

4. Place an SSC-3 bracket on one of the mounting points of the SLB interface bracket (see Figure 6). Depending on the screw size, a flat washer (provided) may be necessary.


Figure 6.

5. Install the projector on the RPA ceiling mount.

6. Install the final SSC-1 bracket and 10-24 x .25" screw (provided) into the hole from Step #1 (see Figure 7).


Figure 7.

7. Install locking device in each of the SSC brackets or connect all five by a cable, making sure the head of each screw is covered (see Figure 8).

Figure 8.