

# INSTALLATION INSTRUCTIONS

## PLASMA DISPLAY STATIC MOUNT

PSM-2024 & 2025 




Figure 1

(1) Plasma Static Mount

(1) Latching Flag

(4) M8 x 45mm Button Head Cap Screws

(4) Mounting Buttons-Black

(1) 10-24 x .5 FH Undercut Screw

(1) Nylon Washer

(1) 10-24 Nylock Nut

(1) 5mm Allen Key

**BEFORE PROCEEDING:** Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

## CAUTION! Plasma Displays are Extremely Fragile.

1. Attach latching flag to mount using the 10-24 Phillips head screw, Nylon washer, and Nylock nut (see Figure 2). Tighten until friction will hold the flag in place.
2. Attach mounting buttons to the display using four M8 x 45 cap screws provided (see Figure 3 & Figure 4).




Figure 2




Figure 3




Figure 4



**CHIEF MANUFACTURING INC.**  
1-800-582-6480 952-894-6280 FAX 952-894-6918  
8401 EAGLE CREEK PKWY, SUITE 700  
SAVAGE, MINNESOTA 55378 USA

8805-000066  
2003 Chief Manufacturing  
[www.chiefmfg.com](http://www.chiefmfg.com)  
09/04

# WARNING

**ALL COMPONENTS MUST BE SECURELY FASTENED TO A STRUCTURAL MEMBER CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF ALL COMPONENTS PLUS THE EQUIPMENT BEING MOUNTED. IF IT CANNOT SUPPORT THIS WEIGHT, THE STRUCTURE MUST BE REINFORCED. THE MAXIMUM WEIGHT TO BE INSTALLED ON THE MOUNT IS 175 POUNDS (79.38 KG).**

3. Securely anchor the plasma static mount to wall studs or supporting framework (see WARNING).
4. Make sure the flag is lowered to the side before attempting to place the display on the mount.
5. With the aid of another person, lift the display up to the mount, align the mounting buttons on the display with the teardrop slots in the mount, and set the display into place (see Figure 5).
6. Position (raise) the flag to secure the display.




Figure 5