



PLASMA DISPLAY MOUNTING BRACKET PDB-111

Unpack and check contents:


- (1) PDB-111 Plasma Mounting Bracket
- (4) M6 - 1.0 X 16mm Button Socket Head Cap Screws
- (4) 5/16 - 18 x 5/8" Hex Head Bolts
- (1) 4mm Short Arm Allen Key
- (4) 3/8" ID x 29/32" OD Flat Washers

Installation Instructions:

1. Align CIRCLED hole pattern on PDB-111 (depending on which plasma you are mounting this bracket to, the 401 will use the (4) outside mounting holes and the 402 will use the (4) inside mounting holes) with pattern on back of Plasma Display, with rectangular slots oriented towards the top of the Plasma Display.
2. Attach to Plasma Display using (4) M6 - 1.0 x 16mm BSHCS.
3. With the aid of another person, lift Plasma Display up to Chief Mount. This Plasma Display can be mounted in one of two positions: one vertical & one horizontal. Each position has its own mounting pattern. There are two rectangular slots oriented at the top of each mounting pattern. Align the two rectangular slots of applicable mounting pattern in Plasma Mounting Bracket, with exposed J-hooks on Chief Mount, and hang Plasma Display onto J-hooks. Attach Plasma Display to Chief Mount using (4) 5/16 - 18 x 5/8" bolts & (4) 3/8" ID x 29/32" flat washers.

PDB-111 bracket drawing

8800-000031



CAUTION: PLASMA DISPLAYS ARE EXTREMELY FRAGILE!

Carefully lay display screen-side-down on a clean, preferably cushioned surface.

