



PLASMA DISPLAY MOUNTING BRACKET PDB-20

Unpack and check contents:

- (1) PDB-20 Plasma Mounting Bracket
- (10) M5 - 0.8 X 12mm Phillips Hex Head Screws with attached washers
- (4) 5/16 - 18 x 5/8" Hex Head Bolts
- (4) 3/8" ID x 29/32" OD Flat Washers

Installation Instructions:



1. Remove plastic covers from each side of display, exposing threaded inserts.
2. Fit PDB-20 Plasma Mounting Bracket flanges over sides of Plasma Display and align four holes (per side) with four inserts.

3. Attach to Plasma Display using (10) M5 - 0.8 x 12mm bolts & (10) M5 flat washers.

4. Reinstall plastic covers.

5. With the aid of another person, lift Plasma Display up to Chief Mount. This Plasma Display can be mounted in one of three positions: two vertical & one horizontal. Each position has its own mounting pattern. There are two rectangular slots oriented at the top of each mounting pattern. Align the two rectangular slots of applicable mounting pattern in Plasma Mounting Bracket, with exposed J-hooks on Chief Mount, and hang Plasma Display onto J-hooks. Attach Plasma Display to Chief Mount using (4) 5/16 - 18 x 5/8" bolts & (4) 3/8" ID x 29/32" flat washers.

PDB-20 bracket drawing.



CAUTION: PLASMA DISPLAYS ARE EXTREMELY FRAGILE!
Carefully lay display screen-side-down on a clean, preferably cushioned surface.

