



## INSTALLATION INSTRUCTIONS

# PSB-2061 PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.  
If you are missing any of the following components, please contact Customer Service at 1-800/582-6480



Figure 1

- (1) Plasma Static Mount Bracket
- (4) Mounting Buttons
- (1) 1/8" Allen Key

- (2) M10-1.5 X 20mm HHCS
- (4) 10-24 Flat head Cap Screws
- (2) M10 Flat Washer

**BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY**

## **CAUTION!** PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Insert a 10-24 flat head cap screw into chamfered hole side of bracket (see Figure 2).
2. Secure mounting button, with chamfered hole of mounting button (larger surface) facing bracket, to bracket and repeat Step 1 and 2 for all four mounting buttons.
3. Slide bracket lip into aluminum extrusion and place bracket gently down onto plasma (see Figure 2).
4. With plasma bracket resting on plasma, push bracket towards the top of the plasma to fully engage in aluminum extrusion and secure using two hex head bolts and M10 flat washers (included). Be careful not to over tighten bolts.
5. With the aid of another person, lift Plasma Display up to the Chief Mount, aligning buttons of mounting brackets with slots in the Chief Mount.
6. Lower safety catch on the Chief Mount to secure Plasma Display, making sure catch is completely engaged.



Figure 2