



INSTALLATION INSTRUCTIONS

PSB-2131

PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.

If you are missing any of the following components, please contact Customer Service at 1-800/582-6480




Figure 1

- (1) Plasma Static Mount Bracket
- (4) Mounting Buttons
- (6) M8-1.25 x 40 mm Button HCS

- (6) 1" Nylon Spacers
- (4) 10-24 Button Head Cap Screws
- (1) 1/8" Allen Key
- (1) M5 Allen Key

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a 10-24 button head cap screw inserted in the circular hole at a spacing of 14", secure mounting button, with chamfered hole of mounting button (larger surface) facing bracket, to bracket (four places) (see Figure 2 & Figure 4).
2. Place Nylon spacers over mounting threads in display (see Figure 3 & Figure 4).
3. Place plasma bracket on display with bent lip towards the plasma (see Figure 3 & Figure 4).

CAUTION: Do not over tighten bolts when securing mount to display

4. Install M8 bolts and tighten (see Figure 3 & Figure 4).
5. With the aid of another person, lift the display up to the Chief Mount, aligning buttons of mounting brackets with the slots in the Chief Mount.
6. Lower safety catch on the Chief Mount to secure the display, making sure the catch is completely engaged.




Figure 2



Figure 3




Figure 4