



INSTALLATION INSTRUCTIONS

PSB-2140 PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.
If you are missing any of the following components, please contact Customer Service at 1-800/582-6480




Figure 1

- | | |
|--|---------------------------------------|
| (1) Plasma Static Mount Bracket | (1) M4 Allen Key |
| (4) Mounting Buttons | (4) 10-24 x .5 Button Head Cap Screws |
| (4) M6-1 x 20mm Button HCS | (1) 1/8" Allen Key |
| (4) Nylon Spacers .5 OD x .3125 ID x .25 | |

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a 10-24 button head cap screw inserted from the back side of bracket, secure mounting button, to bracket (four places) to holes in outer corners with the screw coming into the bracket from the bend side (see Figure 2).
2. Place Nylon spacers over mounting holes on LCD Display, Aligning hole pattern on bracket with pattern
3. Secure bracket to display using the M6 button head cap screws (see Figure 2).
4. With the aid of another person, lift LCD Display up to the Chief Mount, aligning buttons of mounting bracket with slots in the Chief Mount.
5. Lower safety catch on the Chief Mount to secure Plasma Display, making sure catch is completely engaged.




Figure 2