




## INSTALLATION INSTRUCTIONS

# PSB-2280 PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.

If you are missing any of the following components, please contact Customer Service at 1-800/582-6480



- (1) Plasma Bracket
- (4) 10-24 X 1/2" Button Head Cap Screws
- (4) .625 OD x .328 ID x .25 Nylon Spacers
- (1) M5 Allen Key

- (4) Mounting Buttons-Tapped 10-24
- (4) M8 x 30 Button Cap Screws
- (1) 1/8" Allen Key

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

## CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a 10-24 button head cap screw inserted from back side of bracket, secure mounting button, with chamfered hole of mounting button (larger surface) facing bracket, to bracket (four places) (see Figure 2 & Figure 3).
2. Place Nylon spacers on mounting holes and align hole pattern on brackets with pattern on back of Plasma Display (see Figure 4 & Figure 5). Attach bracket utilizing the M8 screws.
3. With the aid of another person, lift Plasma Display up to the Chief Mount, aligning buttons of mounting brackets with slots in the Chief Mount.
4. Lower safety catch on the Chief Mount to secure Plasma Display, making sure latch is completely engaged.




Figure 4




Figure 5