




INSTALLATION INSTRUCTIONS

PSM-2101

PLASMA DISPLAY STATIC MOUNT

Prior to assembly, unpack carton completely and verify contents.

If you are missing any of the following components, please contact Customer Service at 1-800/582-6480



- (1) Plasma Display Static Mount
- (1) 10-24 Nylock Nut
- (1) 10-24 x .5 Undercut FH Screw
- (1) Nylon Washer

Figure 1

- (1) Latching Flag
- (8) Mounting Buttons-Green
- (8) M5 x 25mm BHCS
- (1) 3mm Allen Wrench

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

CAUTION! PLASMA DISPLAYS ARE HEAVY AND EXTREMELY FRAGILE.

1. Attach latching flag to mount using the 10-24 Phillips head screw, the Nylon washer, and the Nylock nut (see Figure 2). Tighten until friction will hold the flag in place.
2. Remove any existing buttons from back of screen. Attach mounting buttons to plasma using M5 screws provided (see Figure 3 & Figure 4).
3. Anchor static mount to wall using wall studs or supporting framework. The mount, when anchored in place, must be capable of supporting 4 times the weight of the display and mount.
4. With the aid of another person, lift display up to the Chief mount, aligning mounting buttons with the teardrop slots and setting into place (see Figure 4).
5. Raise safety latch to secure display (see Figure 5).




Figure 2




Figure 3




Figure 4




Figure 5