
INSTALLATION INSTRUCTIONS

PLASMA DISPLAY STATIC MOUNT

PSM-2113




Figure 1

- | | |
|---------------------------------------|---|
| (1) Plasma Static Mount | (6) Mounting Buttons-Clear Zinc |
| (6) M6 x 25mm Philips Head Cap Screws | (1) Latching Flag |
| (1) Nylon Washer | (1) 10-24 x .5 Flat Head Undercut Screw |
| (1) 10-24 Nylock Nut | |

BEFORE PROCEEDING: Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

CAUTION! Plasma Displays are Extremely Fragile.

1. Attach latching the flag to the mount using the 10-24 Phillips flat head screw, Nylon washer, and Nylock nut (see Figure 2). Tighten until friction will hold the flag in place.
2. Attach mounting buttons to the display using six M6 screws and (see Figure 3 & Figure 4).




Figure 2




Figure 3




Figure 4



CHIEF MANUFACTURING INC.
1-800-582-6480 952-894-6280 FAX 952-894-6918
12800 HIGHWAY 13 SOUTH, SUITE 500
SAVAGE, MINNESOTA 55378 USA

8805-000094 Rev01
2003 Chief Manufacturing
www.chiefmfg.com
10/01/04

WARNING

ALL COMPONENTS MUST BE SECURELY FASTENED TO A STRUCTURAL MEMBER CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF ALL COMPONENTS PLUS THE EQUIPMENT BEING MOUNTED. IF IT CANNOT SUPPORT THIS WEIGHT, THE STRUCTURE MUST BE REINFORCED. THE MAXIMUM WEIGHT TO BE INSTALLED ON THE MOUNT

3. Securely anchor the plasma static mount to wall studs or supporting framework utilizing all six mounting slots (see WARNING).
4. Make sure the flag is lowered before attempting to place the display on the mount.
5. With the aid of another person, lift your display up to the mount, align the mounting buttons on the display with the teardrop slots in the mount, and set the display into place (see Figure 5).
6. Position (raise) the flag to secure the display.




Figure 5