



INSTALLATION INSTRUCTIONS

PLASMA DISPLAY STATIC MOUNT

PSM-2160 



- (1) Bracket, Plasma Mounting, Static
(4) Mounting Buttons-Green
(4) Mounting Buttons-Yellow
(1) Nylon Washer .5 OD x .313 ID x .031
(4) M4 x 20mm Philips Head Screws

Figure 1

- (1) Latching Flag
(1) 10-24 Nylock Nut
(1) 10-24 x .5 Undercut FH Screw
(4) M5 x 70mm Philips Head Screws

BEFORE PROCEEDING: Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a #10-24 flat head cap screw inserted from chamfered hole side of latching flag, Nylon washer between safety latch and mount, and 10-24 Nylock nut, install the safety latch loose enough to move but tight enough to remain in place when raised.
2. Attach mounting buttons to plasma using the enclosed screws and mounting buttons. Use 4 yellow buttons with the 20mm screw on the 4 inside mounting holes and use the green buttons with the 70mm screws on the outside mounting holes (see Figure 2 & Figure 3).




Figure 2




Figure 3



CHIEF MANUFACTURING INC.
1-800-582-6480 9 52-894-6280 FAX 952-894-6918
8401 EAGLE CREEK PKWY, STE 700
SAVAGE, MINNESOTA 55378 USA

8805-000056
2003 Chief Manufacturing
www.chiefmfg.com
08/04

WARNNG!

ALL COMPONENTS MUST BE SECURELY FASTENED TO A STRUCTURAL MEMBER CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF ALL COMPONENTS PLUS THE EQUIPMENT BEING MOUNTED. IF IT CANNOT SUPPORT THIS WEIGHT, THE STRUCTURE MUST BE REINFORCED. THE MAXIMUM WEIGHT TO BE INSTALLED ON THE MOUNT IS 175 POUNDS (79.38 KG).

3. Securely anchor plasma static mount to the wall using wall studs or supporting framework (see WARNING).
4. Make sure the flag is lowered to the side before attempting to place the plasma on the mount.
5. With the aid of another person, lift the plasma display up to the mount, align the mounting buttons on the plasma with the teardrop slots in the mount, and set the plasma into place (see Figure 4).
6. Position (raise) the flag to secure the plasma (see Figure 4).




Figure 4