

INSTALLATION INSTRUCTIONS

INSTALLATION INSTRUCTIONS

PSM 2630

PLASMA DISPLAY STATIC MOUNT




Figure 1

- | | |
|---|---|
| (1) Plasma Static Mount | (1) Screw, Undercut 10-24 x .5 FH (Attached to Mount) |
| (1) Flag, Latching (Attached to Mount) | (1) Nut, Nylock 10-24 (Attached to Mount) |
| (6) Mounting buttons, Silver (.242" Hole) | (6) Screw, Button Head Cap, M6 x 25mm |
| (1) Key, Allen 4MM | (1) Washer, Nylon, .5" ODx.312" IDx.0312" (Attached to Mount) |

BEFORE PROCEEDING: Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

WARNING! THE MOUNT, WHEN ANCHORED IN PLACE, MUST BE CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF THE PLASMA AND MOUNT.

1. Attach mounting buttons to display using six M6 cap screws provided (see Figure 2 and Figure 3).
2. Securely anchor the mount to the wall using wall studs or supporting framework.
3. Make sure the flag is lowered to the side before attempting to place the display on the mount.
4. With the aid of another person, lift the display up to the mount, align the mounting buttons on the display with the teardrop slots in the mount, and set the display into place (see Figure 4).
5. Position (raise) the flag to secure the display.




Figure 2




Figure 3




Figure 4