

INSTALLATION INSTRUCTIONS

SL151 BPAC KIT


SL151 BOTTOM PANEL ANCHOR CABLE KIT

Unpack carton and verify kit contents. If any listed parts are missing, contact a Chief Customer Service representative.



WARNING: IMPROPER INSTALLATION CAN LEAD TO EQUIPMENT FALLING CAUSING SERIOUS PERSONAL INJURY AND DAMAGE TO EQUIPMENT! DO NOT substitute hardware. Use only hardware supplied by manufacturer!

TOOLS / PARTS REQUIRED FOR INSTALLATION



INSTALLATION




WARNING: OVERTIGHTENING OF SCREWS CAN DAMAGE PARTS AND LEAD TO SERIOUS PERSONAL INJURY AND DAMAGE TO EQUIPMENT! DO NOT overtighten screws when installing kit.

1. Replace bottom panel anchor cable (A) onto end of ceiling panel rod, using two 8-32 x 5/16" Phillips head screws (B) and one 8-32 nut (C).



CAUTION: Damage to parts will occur if retainer clip is not correctly aligned with the ceiling panel and attached as shown in the following figure.



Chief® is a registered trademark of Milestone AV Technologies. All rights reserved.



Milestone AV Technologies, and its affiliated corporations and subsidiaries (collectively, "Milestone"), intend to make this manual accurate and complete. However, Milestone makes no claim that the information contained herein covers all details, conditions or variations, nor does it provide for every possible contingency in connection with the installation or use of this product. The information contained in this document is subject to change without notice or obligation of any kind. Milestone makes no representation of warranty, expressed or implied, regarding the information contained herein. Milestone assumes no responsibility for accuracy, completeness or sufficiency of the information contained in this document.