

# INSTALLATION INSTRUCTIONS

## ELELG50-PRO Mounting Bracket

Prior to assembly, unpack carton completely and verify contents. If you are missing any of the following components, please contact Technical Support at 1-800-776-5768.

- (1) BRACKET, PLASMA STATIC MOUNT
- (4) Mounting Buttons – Black Threaded
- (6) M5 x 20 Phillips HCS




Figure 1

- (6) .625 OD X .325 ID X .250 Nylon Spacers
- (4) 10-24 Button Head Cap Screws
- (1) 1/8" Allen Key

**CAUTION: PLASMA DISPLAYS ARE EXTREMELY FRAGILE!**

### READ INSTALLATION INSTRUCTIONS COMPLETELY BEFORE PROCEEDING

1. Using a 10-24 button head cap screw inserted in the non-chamfered hole at a spacing of 14", secure mounting button, with chamfered hole of mounting button (larger surface) facing bracket, to bracket (four places). (See Figures 2 & 3)
2. Place nylon spacers over mounting holes and lay bracket on top of the spacers with the bent lip of the bracket towards the plasma. Attach bracket utilizing the enclosed M5 screws (See Figures 4 & 5).
3. With the aid of another person, lift Plasma Display up to the Chief Mount, aligning buttons of mounting brackets with slots in the Chief Mount.
4. Lower safety catch on the Chief Mount to secure Plasma Display, making sure catch is completely engaged.





Figure 2



ATTACH MOUNTING BUTTONS  
IN THESE HOLES

Figure 3





Figure 4



USE THESE MOUNTING HOLES  
TO ATTACH BRACKET TO PLASMA

Figure 5