



INSTALLATION INSTRUCTIONS


PDB-43

PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.

If you are missing any of the following components, please contact Customer Service at 1-800/582-6480

(1) PDB-43 Plasma Mounting Bracket



(6) M8 - 1.25 x 12mm Button Head Screws
(4) Ø 3/8" ID x Ø 29/32" OD Flat Washers

(4) 5/16 - 18 x 5/8" Hex Head Bolts
(1) 5mm Allen Key

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

CAUTION!

**PLASMA DISPLAYS ARE EXTREMELY FRAGILE.
CAREFULLY LAY DISPLAY SCREEN-SIDE-DOWN
ON A CLEAN, PREFERABLY CUSHIONED, SURFACE.**

1. Align hole pattern on PDB-43 with pattern on back of Plasma Display, with rectangular slots oriented towards the top of the Plasma Display.
2. Attach to Plasma Display using (6) M8 - 1.25 x 12mm .
3. With the aid of another person, lift Plasma Display up to Chief Mount.

This Plasma Display can be mounted in one of two positions: one vertical & one horizontal. Each position has its own mounting pattern. There are two rectangular slots oriented at the top of each mounting pattern. Align the two rectangular slots of applicable mounting pattern in Plasma Mounting Bracket, with exposed J-hooks on Chief Mount, and hang Plasma Display onto J-hooks. Attach Plasma Display to Chief Mount using (4) 5/16 - 18 x 5/8" bolts & (4) Ø 3/8" ID x Ø 29/32" flat washers.