



## INSTALLATION INSTRUCTIONS

# PSB-2130

## PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.

If you are missing any of the following components, please contact Customer Service at 1-800/582-6480



- (1) Plasma Static Mount Left Bracket
- (4) Mounting Buttons
- (4) M8-1.25 x 35mm BHCS
- (1) 5mm Allen Key

Figure 1

- (1) Plasma Static Mount Right Bracket
- (4) 10-24 Flat head Cap Screws
- (1) 1/8" Allen Key
- (4) 20mm Nylon Spacers

**BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY**

## **CAUTION!** PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a 10-24 flat head cap screw inserted from chamfered hole side of bracket, secure mounting button, with chamfered hole of mounting button (larger surface) facing bracket, to bracket (four places). See Figure 2.
2. Place nylon spacers on mounting holes and align hole pattern on brackets with pattern on back of Plasma Display (see Figure 2).
3. With the aid of another person, lift Plasma Display up to the Chief Mount, aligning buttons of mounting brackets with slots in the Chief Mount.
4. Lower safety catch on the Chief Mount to secure Plasma Display, making sure catch is completely engaged.




Figure 2