



INSTALLATION INSTRUCTIONS

PSB-2330

PLASMA DISPLAY MOUNTING BRACKET

Prior to assembly, unpack carton completely and verify contents.

If you are missing any of the following components, please contact Customer Service at 1-800/582-6480




Figure 1

- (1) Plasma Static Mount Bracket-Left
- (4) Mounting Buttons-Black Nylon
- (8) 20mm Nylon Spacers
- (8) M6 x 25mm Philips Head Cap Screws
- (4) 5/16-18 X 1-1/2" Hex Head Cap Screw

- (1) Plasma Static Mount Bracket-Right
- (4) 5/16-18 x 3" Hex Head Cap Screw
- (4) 5/6-18 Ny-lock Nuts
- (8) 1/4" Nylon Spacers

BEFORE PROCEEDING, READ INSTALLATION INSTRUCTIONS COMPLETELY

CAUTION! PLASMA DISPLAYS ARE EXTREMELY FRAGILE.

1. Using a 5/16-18 x 3" hex head screw inserted from back, bent lip side of bracket, secure each mounting button with two 20mm Nylon spacers under the button to bracket (four places) using the 5/16-18 Nylock nuts (see Figure 2 & Figure 3). For units without a power box on the back of the screen, use the 1-1/2 hex head screws without the spacers.
2. Align the hole pattern on the brackets with the pattern on the back of the display and attach using enclosed Philips head screws with one 1/4" spacer under the bracket at each mounting point (see Figure 3, Figure 4, & Figure 5).
3. With the aid of another person, lift the display up to the Chief Mount, aligning buttons of mounting brackets with slots in the Chief Mount.
4. Lower safety catch on the Chief Mount to secure the display, making sure catch is completely engaged.




Figure 2




Figure 3




Figure 4




Figure 5