

# INSTALLATION INSTRUCTIONS

## DISPLAY STATIC MOUNT

### PSM-2532




Figure 1

- |                                |                                     |
|--------------------------------|-------------------------------------|
| (1) Static Mount Bracket       | (1) Latching Flag                   |
| (1) 10-24 x .5 Flat Head Screw | (1) Nylon Washer                    |
| (4) Mounting Buttons           | (4) M8 x 45mm Button Head Cap Screw |
| (4) Spacer                     | (1) M5 Allen Key                    |

**BEFORE PROCEEDING:** Unpack the carton, verify contents shown in Figure 1 and read installation instructions completely. If you are missing any of the listed components, please contact Customer Service at 1-800/582-6480.

## CAUTION! Displays are Extremely Fragile.

1. Attach the latching flag to the mount using the 10-24 Phillips flat head screw, Nylon washer, and Nylock nut (see Figure 2). Tighten until friction will hold the flag in place.
2. Attach the mounting buttons to the display using M8 screws and spacers provided (see Figure 3 & Figure 4).




Figure 2




Figure 3




Figure 4



**CHIEF MANUFACTURING INC.**  
 1-800-582-6480 952-894-6280 FAX 952-894-6918  
 8401 EAGLE CREEK PKWY, STE. 700  
 SAVAGE, MINNESOTA 55378 USA

8805-000110 RevB  
 2004 Chief Manufacturing  
[www.chiefmfg.com](http://www.chiefmfg.com)  
 11/04

# WARNING

**ALL COMPONENTS MUST BE SECURELY FASTENED TO A STRUCTURAL MEMBER CAPABLE OF SUPPORTING 4 TIMES THE COMBINED WEIGHT OF ALL COMPONENTS PLUS THE EQUIPMENT BEING MOUNTED. IF IT CANNOT SUPPORT THIS WEIGHT, THE STRUCTURE MUST BE REINFORCED. THE MAXIMUM WEIGHT TO BE INSTALLED ON THE MOUNT IS 175 POUNDS (79.38 KG).**

3. Securely anchor the static mount to wall studs or supporting framework (see WARNING).
4. Make sure the flag is lowered before attempting to place the screen on the mount.
5. With the aid of another person, lift the display up to the mount, align the mounting buttons on the screen with the teardrop slots in the mount, and set the screen into place (see Figure 5).
6. Position (raise) the flag to secure the display.




Figure 5