

PXR Software Updates:

v40 (April 22, 2011)

- Fixed a bug that would, in certain cases, make the unit look for a tilt limit status when it shouldn't, causing the unit to stall out until the tilt limit was triggered.
- Fixed a bug that would cause the unit to stop and become unresponsive with no blink error code.
- Fixed a bug that would allow extremely thick/heavy screens to cause the tilt home position to drift.
- Changed how the PXR responds in Learn Mode. The unit will now exit Learn Mode immediately when the cycling is interrupted and begin blink 5 times indicating the unit did not successfully complete the Learn Mode.
- Changed the 6 blink error to a non-permanent error. This allows the error to be temporarily cleared with the stop button.
- Changed the trip points of the 4 blink error to better accommodate thick/ heavy screens as well as ultra thin and light screens.
- Added Emergency service extend. This allows the unit to be extended out with the remote at any time.

v25 (September 1, 2010)

First official release.